

# SEACOMP


## END-OF-LIFE NOTIFICATION (EOL)

<b><u>EOL NUMBER</u></b> EOL23001	<b><u>DATE</u></b> 17 NOV 2023
<b><u>CUSTOMER(S)</u></b> All	
<b><u>PROJECT(S) AFFECTED</u></b> DT050ATFT, DT050ATFT-PTS, DT050ATFT-TS	
<b><u>EFFECTIVE DATE / OTHER REFERENCE</u></b> 16 November 2023	

DETAILS									
<b><u>REASON FOR TERMINATION</u></b> TFT Driver end of life									
<b><u>LAST TIME BUY</u></b> 16 November 2023									
<b><u>REPLACEMENT PRODUCT</u></b> DT050ATFT series (ILI6122 TFT driver) replaced with DT050BTFT series (ILI6137 TFT driver): <table><tr><td>DT050ATFT</td><td>→</td><td>DT050BTFT</td></tr><tr><td>DT050ATFT-PTS</td><td>→</td><td>DT050BTFT-PTS</td></tr><tr><td>DT050ATFT-TS</td><td>→</td><td>DT050BTFT-TS</td></tr></table>	DT050ATFT	→	DT050BTFT	DT050ATFT-PTS	→	DT050BTFT-PTS	DT050ATFT-TS	→	DT050BTFT-TS
DT050ATFT	→	DT050BTFT							
DT050ATFT-PTS	→	DT050BTFT-PTS							
DT050ATFT-TS	→	DT050BTFT-TS							

Thank you for your continued interest in SEACOMP products and services. For additional assistance or questions, please contact SEACOMP Customer Service at [sales@seacomp.com](mailto:sales@seacomp.com) or the Sales contact you are working with.

Sincerely,  
For and on behalf of SEACOMP



Jamie Priest  
Interim Director of Engineering

